



PRS 2 Pot Left Handed Wiring Diagram - 500k Reverse Taper Pots



 = Ground