


Fender Mustang Wiring Diagram

250k Pots



⏏ = Ground