


Fender Bullet Mustang Wiring Diagram

500k Pots



≡ =Ground