

Yamaha PAC1611MS Mike Stern Wiring Diagram

500k Pots

3 Way Switch

